	NT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILDING	PLE CONSTRUCTION / OT - MAIN BUILDING 01	(X3) DATE S	
IAME OF	PROVIDER OR SUPPLIER	445181	B. WING_		10/6	04/2011
	HAL HILLS NURSING (CENTER	20	EET ADDRESS, CITY, STATE, ZI 34 COCHRAN RD ARYVILLE, TN 37803	PCODE	, , , , ,
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES 'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE AC CROSS-REFERENCED TO DEFICIENT	TION SHOULD BE THE APPROPRIATE	(X5) COMPLETION DATE
K 038 SS=D	Exit access is arran	FETY CODE STANDARD ged so that exits are readily es in accordance with section	K 038	K 038: NFPA 101 Life Standard 1) What corrective actions correct this alleged deficie a) The two rolling carts we the kitchen exit door on 10	will be taken to nt practice? ere removed from	
K 050 SS=F	Based on observati exit access was read The findings include Observation on Octorevealed two (2) rolli of the kitchen exit do NFPA 101 LIFE SAF	: ober 4, 2011 at 10:00 a.m. ng dish carts stored in front	K 050	2) Identify residents that he affected by the alleged a) Residents in the facility to be affected. b) The inspections of the facility were inspected were readily accessible.	ave the potential to deficient practice? ity have the potential e exit doors in the d to ensure all exits	
	that drills are part of Responsibility for pla assigned only to comqualified to exercise I conducted between 9 announcement may balarms. 19.7.1.2	vith procedures and is aware established routine. Inning and conducting drills is petent persons who are eadership. Where drills are PM and 6 AM a coded be used instead of audible		3) What measures will be what systemic changes you ensure that the deficient precur? a) The maintenance superexit doors monthly for 3 mexits are readily accessible. 4) How the corrective action monitored to ensure the denot recur and what quality will be put into place?	visor will audit all onths to ensure all on(s) will be ficient practice will	
<u> </u>	Based on observation staff members are far procedures. The findings include: Observation during a	not met as evidenced by: n, the facility failed to assure miliar with proper fire drill fire drill conducted on :05 a.m. revealed a staff		a) The Maintenance supervesults of the audit to the P Improvement Committee for	crformance	
RATORY L	DIRECTOR'S OR PROVIDER	SUPPLIER REPRESENTATIVE'S SIGNA	TURE.	1 1 TITLE	· · · · · · · · · · · · · · · · · · ·	6) DATE

A CMS-2567(02-99) Previous Versions Obsolete

Event ID: BNDL21

Facility ID: TN0502

If continuation sheet Page 1 of 6

DEPARTMENT OF HEALTH AND HUM/ **ERVICES** CENTERS FOR MEDICARE & MEDICAID SERVICES

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER;

PRINTED: 10/06/2011 FORM APPROVED OMB NO. 0938-0391

(X2) MULTIPLE CONSTRUCTION A. BUILDING 09 - MAIN BUILDING 01

(X3) DATE SURVEY COMPLETED

445181

B. WING

10/04/2011

AME OF PROVIDER OR SUPPLIER

FATEMENT OF DEFICIENCIES NO PLAN OF CORRECTION

COLONIAL HILLS NURSING CENTER

STREET ADDRESS, CITY, STATE, ZIP CODE 2034 COCHRAN RD

		1224-02-03-03-03-03-03-03-03-03-03-03-03-03-03-	MA	ARYVILLE, TN 37803				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DI (EACH DEFICIENCY MUST BE PRE REGULATORY OR LSC IDENTIFYIN	CEDED BY EUL	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X6) COMPLETION DATE			
K 051 SS=D	member placing a wheelchair pused as a simulated fire room a door during the fire drill exercise NFPA 101 LIFE SAFETY CODE A fire alarm system with approvidevices or equipment is installed NFPA 72, National Fire Alarm Confective warning of fire in any particular fire alarm initiation, auto extinguishing system operation. patient sleeping areas may be on that manual pull stations are with nurse's stations. Pull stations are path of egress. Electronic or writests are available. A reliable sepower is provided. Fire alarm symaintained in accordance with National fire is remote annunciation of system to an approved central station.	ed components, d according to code, to provide art of the building. arm system is by matic detection or Pull stations in mitted provided in 200 feet of the located in the ten records of cond source of stems are FPA 72 and readily available. The fire alarm ation. 19.3.4,	K 050	b) The Performance Improvement Committee will review these results; and if deemed necessary by the committee, additional education may be provided; the process evaluated/revise and/or the audits reviewed, for three months or until 100% compliance is achieved. K 050: NFPA 101 Life Safety Code Standard 1) What corrective actions will be taken to correct this alleged deficient practice? a) The staff was counsel on 10/04/2011 on the proper action during a fire drill to ensure resident safety. 2) Identify residents that have the potential to be affected by the alleged deficient practice? a) Residents in the facility have the potential to be affected. b) The staff was in-service on 10/21/2011 on the proper procedure during the fire drill to ensure resident safety. 3) What measures will be put into place or what systemic changes you will make to ensure that the deficient practice does not recur? a) The maintenance supervisor will do fire drills 3 times a month for 3 months.	10/6/30			
si a T	his STANDARD is not met as end assed on observation, the facility moke detectors were located at In air supply (NFPA 72, 2-3.5.1). The findings include:	failed to assure east 3 feet from		4) How the corrective action(s) will be monitored to ensure the deficient practice will not recur and what quality assurance program will be put into place?				
-	bservation on October 4, 2011 a	t 11:00 a.m.		a) The Maintenance supervisor will report the results of the fire drills to the Performance Improvement Committee for 3 months				
.ws-2567(i	2-99) Previous Versions Obsolete	Event ID: BNDL21	Facility ID	0: TN0502 If continuation sheet P	200 2 of A			

DEPARTMENT OF HEALTH AND HUM/ ERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/06/2011 FORM APPROVED OMB NO. 0938-0391

10/04/2011

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER;

(X2) MULTIPLE CONSTRUCTION

A. BUILDING

B. WING

(X3) DATE SURVEY

445181

01 - MAIN BUILDING 01

COMPLETED

NAME OF PROVIDER OR SUPPLIER

COLONIAL HILLS NURSING CENTER

STREET ADDRESS, CITY, STATE, ZIP CODE 2034 COCHRAN RD

		1	MARYVILLE,	TN 37803	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PRO (EACH	OVIDER'S PLAN OF CORRECTION CORRECTIVE ACTION SHOULD BE REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
K 051	Continued From page 2 revealed the smoke detector installed above fi door number 4 on the 300 half was installed within three (3) feet of the air diffuser.	re K 051	will revie	erformance Improvement Committee w these results; and if deemed by the committee, additional	
K 069 SS=D	NFPA 101 LIFE SAFETY CODE STANDARD	K 069	education evaluated	may be provided; the process /revise and/or the audits reviewed, for this or until 100% compliance is	10/5 You
	This STANDARD is not met as evidenced by: Based on observation and interview, the facilit failed to assure commercial cooking equipmen was provided with a drip tray and collection container.	y t	1) What correct thin	orrective actions will be taken to is alleged deficient practice?	
K 147 SS=D	The findings include: Observation and interview with the Maintenance Director in the kitchen, on October 4, 2011 at 10:00 a.m. confirmed the exhaust hood system drip tray was removed and did not provide a grease collection container on the system. Observation and interview with the Maintenance Director in the kitchen, on October 4, 2011 at 10:00 a.m. revealed the installed cooking appliances were not properly placed under the hood and was not protected by the hoods extinguishing system. NFPA 101 LIFE SAFETY CODE STANDARD Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code, 9.1.2 This STANDARD is not met as evidenced by: Based on observation, the facility failed to assure electrical wiring is installed in accordance with NFPA 70. The findings include:	K 147	2) Identify be affected a) Resid to be b) The m smoke will m within 3) What me what system ensure that recur? a) The mai the smoke of there are no feet of a air 4) How the monitored to	corrective action(s) will be o ensure the deficient practice will d what quality assurance program	

EPARTMENT OF HEALTH AND HUMAN RVICES ENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/06/2011 FORM APPROVED OMB NO. 0938, 0201

TEMENT OF DEFICIENCIES (X1) PROVIDE		OSCINDIOES				0.0938-039			
PLAN	OF CORRECTION	IDENTIF	ER/SUPPLIER/CLIA CATION NUMBER:	1	'nrding Moraibri	E CONSTRUCT	ON BUILDING 01	(X3) DATE COMP	SURVEY
	* *		445181	B. W	ING			1 .	
NE OF PROVIDER OR SUPPLIER CONIAL HILLS NURSING CENTER		_!	STREE	T ADDRESS, C	ITY, STATE, ZIP CODE	10/	04/2011		
					100000000000000000000000000000000000000	COCHRAN R RYVILLE, TN			
(4) ID REFIX TAG	(EACH DEFICIENC REGULATORY OR	AYEMENT OF D Y MUST BE PRE LSC IDENTIFYIN	CEDED BY ELLI	ID PREF TAG	TIX .	(EACH CO	PER'S PLAN OF CORRI RRECTIVE ACTION SI ERENCED TO THE AP DEFICIENCY)	HOULD BE	(X5) COMPLETION DATE
(147	Continued From particle Continued From particle Continued From particle Continued Cont	tober 5, 201 ectrical junct the attic are	ion haves installed	К	147	results of	nintenance supervisor the audit of the smok mance Improvement	e defectors to	
	21 24			(S)		will revie necessary education evaluated	rformance improvem we these results; and if by the committee, ad may be provided; the revise and/or the aud ths or until 100% con	deemed ditional process its reviewed, fo	
						Standard 1) What co	PA 101 Life Safety	be taken to	
				1921		a) The e instal	s alleged deficient pro xhaust hood system of led on 10/21/2011. ooking appliances we	Irip tray was	
						the ex	haust hood system so suishing system prote	that hood-	
						2) Identify be affected	residents that have th by the alleged defici	ent practice?	
						a) Reside	ents in the facility hav affected.	e the potential	5/
						what syster	asures will be put int nic changes you will the deficient practice	make to	
						inspect/and	ntenance supervisor v it the drip tray is in pl nsure that the drip tra	lace for 3	

DEPARTMENT OF HEALTH AND HUMA PRINTED: 10/06/2011 **ERVICES** CENTERS FOR MEDICARE & MEDICAID SERVICES FORM APPROVED OMB NO. 0938-0391 TATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA ND PLAN OF CORRECTION (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 - MAIN BUILDING 01 B. WING 445181 VAME OF PROVIDER OR SUPPLIER 10/04/2011 STREET ADDRESS, CITY, STATE, ZIP CODE COLONIAL HILLS NURSING CENTER 2034 COCHRAN RD MARYVILLE, TN 37803 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PREFIX PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (X5) COMPLETION DATE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) Continued From page 3 K 147 Observation on October 5, 2011 at 2:15 p.m. revealed two (2) electrical junction boxes installed b) The maintenance supervisor will above the ceiling in the attic area on 300 hall area inspect/audit cooking appliance in the kitchen have no protective covers. to ensure that the cooking appliances are under the exhaust hood system. 4) How the corrective action(s) will be monitored to ensure the deficient practice will not recur and what quality assurance program will be put into place? a) The Maintenance supervisor will report the results of the audit of the drip tray and the cooking appliances are in the proper position and report the results to the Performance Improvement Committee for 3 months. b) The Performance Improvement Committee will review these results; and if deemed necessary by the committee, additional education may be provided; the process evaluated/revise and/or the audits reviewed, for three months or until 100% compliance is 11/1/5011 achieved. K 147: NFPA 101 Life Safety Code Standard 1) What corrective actions will be taken to correct this alleged deficient practice? a) The protective covers on the two electric junction box were installed on 10/05/2011, 2) Identify residents that have the potential to be affected by the alleged deficient practice? Residents in the facility have the potential

to be affected.

The maintenance supervisor audited the junction boxes in the ceiling on the 300-